


Peak-Picker Application for Excel

For the analysis if infrared spectra of DCI/HCI

Sandor Kadar, Ph.D.

Department of Chemistry

Wellesley College



A spectrum can have 8 sections: one set of fundamental transitions for each of the four possible molecules (D³⁷Cl, D³⁵Cl, H³⁷Cl, H³⁵Cl), and the corresponding first overtones.

This application allows you to zoom in a section of the spectrum and collect the corresponding m and wavenumber data. You select the peaks by clicking on them and the program assigns the corresponding m value either automatically or you can do it manually. You analyze one set of

transitions (e.g. D³⁷Cl fundamental) at a time. Follow the steps in the form to collect data. The icons provide additional help.



The video version of this manual is available from:


http://chemistry4.me/PeakPicker.asp

The program can be downloaded from:

http://chemistry4.me/PeakPicker app.asp


Open the application


- 2. Click on the load your data button to
- 3. Select the correct filter
 - For the PE instrument select "*.asc"
 - For the Bruker instrument select "*.dpt", and open your experimental file



4. The spectrum will be displayed. Identify sections of the spectrum.

- From the drop-down list select the a section of the spectrum to be analyzed (e.g. "D35Cl fundamental" for the n=0-> n=1 transition of the D³⁵Cl molecule)
 - the selection will rescale the spectrum to show the part that you selected
 - only sections of the DCI/HCI spectrum will show up in the drop-down list for which the experimental data file has information for
- 6. Adjust the scales if necessary by entering the new minimum and maximum values for the x and y axes and click on the button.
 - Click on the Reset axes button to show the whole spectrum again, if you need it
- 7. Adjust the vertical zoom to make the peaks that you analyze fill the graph






- You can track the m values and the corresponding wavenumbers one of two ways: manually or automatically.
 For auto change of the m values:
 - a. Check the option
 - b. Then click on the peak which you think corresponds to m = 1. The value of m is incremented to m = 2.
 - If the point is crrect, clickon OK, othwise click on NO and try again.
 - d. Click on the peak m = 2.
 - e. Continue until you are done with the R branch
 - f. Select
 (you need to click on it twice; the first click clears the auto-increment option)
 - g. Then click on the peak which you think corresponds to m = -1. The value of m is decremented to m = -2.
 - h. Continue until you are done with the P branch

For manual adjustment of *m*, use the spin control:


- a. Dial the *m* value
- b. Click on the corresponding peak
- c. Change the value of *m* by clicking up for the R branch
- d. Continue until you collected all *m* values for the R branch
- e. Click on the button and once on the down arrow to set m = -1
- f. Click on the first peak on the P branch
- g. Keep changing the m value and clicking on the corresponding peak
 - If you make a mistake, just keep clicking until you get it right and then change *m*.




When you collected all the data, click on the

Save your data in the Data worksheet

button to save your data. This will save your data under the corresponding section in the "Data" worksheet and below the points in rows 35-39 shows the constants for a third-order polynomial fit.





Below each set of data you can enter the formulae for the cubic polynomial fitting as shown in the figure. Note, that the function LINEST is used, for example:

=INDEX(LINEST(J2:J31,I2:I31^{1,2,3}), 1,2)

J2:J31 is the range of y values
I2:I31 is the range of x values
2 (at the end) refers to constant C
So this formula will calculates C (the quadratic term)

